

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10A

INITIAL STATE




FIG.10B

AUTO AIMING COMPLETION STATE
DISPLAY INDICATION [LR 0.0]




FIG.11A

INITIAL STATE




FIG.11B

AUTO AIMING COMPLETION STATE (STILL TILTED BY 0.5°)
DISPLAY INDICATION [L 0.5]




FIG.11C

MANUAL AIMING COMPLETION STATE
DISPLAY INDICATION LR 0.0




FIG.12




FIG.13




FIG.14A

INITIAL STATE




FIG. 14B

AUTO AIMING COMPLETION STATE (DETECTION AREA NOT EQUAL IN LEFT AND RIGHT)

DISPLAY INDICATION




FIG.14C

MANUAL AIMING COMPLETION STATE

DISPLAY INDICATION LR 0.0

